

Proration Schedule

<u>Points/40</u>	<u>Factor</u>	<u>cfs/40</u>	<u>gpm/acre</u>	<u>gpm/40</u>
1	0.00013	0.01	0.1	2
2	0.00036	0.01	0.2	6
3	0.00066	0.03	0.3	12
4	0.00101	0.04	0.5	18
5	0.00141	0.06	0.6	25
6	0.00186	0.07	0.8	33
7	0.00234	0.09	1.0	42
8	0.00286	0.11	1.3	51
9	0.00341	0.14	1.5	61
10	0.00399	0.16	1.8	72
11	0.00461	0.18	2.1	83
12	0.00525	0.21	2.4	94
13	0.00592	0.24	2.7	106
14	0.00661	0.26	3.0	119
15	0.00734	0.29	3.3	132
16	0.00808	0.32	3.6	145
17	0.00885	0.35	4.0	159
18	0.00964	0.39	4.3	173
19	0.01046	0.42	4.7	188
20	0.01129	0.45	5.1	203
21	0.01215	0.49	5.5	218
22	0.01303	0.52	5.8	234
23	0.01393	0.56	6.3	250
24	0.01485	0.59	6.7	267
25	0.01578	0.63	7.1	283
26	0.01674	0.67	7.5	301
27	0.01771	0.71	8.0	318
28	0.01871	0.75	8.4	336
29	0.01972	0.79	8.8	354
30	0.02075	0.83	9.3	372
31	0.02179	0.87	9.8	391